



Date: 4/3/2023

Region: 4C

FAC ID: VA012

CSS No.: 92493

Maximo Work Order No.: 12361

Asset #: NA

Original Work Request:

No Hot Water, Replace Circulating Pump

Description of Repairs Needed:

Labor and material to a.) replace the 52722512 Grundfos Circulator Pump - CROSS PUMP

Material List:

(1) 52722512 Grundfos Circulator Pump

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
8	\$1,045.71	\$1,992.71	\$3,038.42



GRUNDFOS

NONSUBMERSIBLE CIRCULATION PUMP

TYPE: UPS26-99FC

P/N: 52722512 P1

1x115V

PC: 1809



60Hz

20µF

I_{max} (A) | P_{max} (W)

1.30 | 150

1.50 | 179

1.80 | 197

CSA ENC 2



Class F
THERMALLY
PROTECTED

FOR INDOOR
USE ONLY

MAX FLUID TEMP 230 °F



99K4

LISTED