



Date: 5/11/2023

Region: 4C
FAC ID: WV007

CSS No.: 92586
Maximo Work Order No.: 12546

Asset #: NA

Original Work Request:

Repair men's restroom door handles 1st floor all the parts from inside are missing the 2nd floor handle is bent and jammed.

Description of Repairs Needed:

Labor and material to a.) Replace Door Handles (Schlage Commercial Push/Pull Latch (HL6-2 626 A HL6)) on Men's Restroom Stalls (1st & 2nd Floors)

Material List:

(2) Schlage Commercial Push/Pull Latch (HL6-2 626 A HL6)

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
3	\$396.00	\$1,234.00	\$1,630.00

