



Date: 3/28/2023

Region: 4A
FAC ID: PA118

CSS No.: 92623
Maximo Work Order No.: 12374

Asset #: NA

Original Work Request:

The MEP sliding motorized gate is not functioning properly. The gate is opening and closing on its own and sometimes will not close. This is causing a security issue for the facility. Repair sliding motorized gate so it will open and close under normal conditions.

Description of Repairs Needed:

Labor to a.) Diagnose the MEP Sliding Motorized Gate at the PA118.

Material List:

NA

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
16	\$1,632.00	\$0.00	\$1,632.00