



Date: 3/27/2023

Region: 4A
FAC ID: NY070

CSS No.: 92624
Maximo Work Order No.: 12375

Asset #: NA

Original Work Request:

Perform state certified backflow annual inspection for the 3 each backflow devices

Description of Repairs Needed:

Labor to a.) test (3) backflow devices AT NY070 and provide reports to the 99th RD.

Material List:

NA

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
5	\$660.00	\$0.00	\$660.00