



Date: 4/25/2023

Region: 4C
FAC ID: WV020

CSS No.: 92640
Maximo Work Order No.: 12547

Asset #: NA

Original Work Request:

Repair 1st toilet in women's room - isn't flushing correctly.

Description of Repairs Needed:

Labor and material to a.) replace and install the Diaphragm Assembly: Fits Sloan Brand, For Regal(R)/Royal(R), 3.5 gpf Size, 3.5 gpf Gallons per Flush

Material List:

(1) Diaphragm Assembly: Fits Sloan Brand, For Regal(R)/Royal(R), 3.5 gpf Size, 3.5 gpf Gallons per Flush

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
4	\$511.53	\$102.96	\$614.49