



Date: 5/10/2023

Region: 4A
FAC ID: NY010

CSS No.: 92784
Maximo Work Order No.: 12526

Asset #: 3069

Original Work Request:

Trouble shoot and repair -- Unit J-1502000-04 1-pc Air Handler.

Description of Repairs Needed:

Labor to a.) Supply (8) hours of labor diagnostic for inoperative ERV (heat wheel)

Material List:

NA

Equipment List:

NA

PM WO History:

11835

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
8	\$1,117.00	\$0.00	\$1,117.00