



Date: 4/27/2023

Region: 4A
FAC ID: PA062

CSS No.: 92818
Maximo Work Order No.: 12531

Asset #: NA

Original Work Request:

Repair chemical pot feeder located in mechanical room. The chemical pot feeder is rusted and unable to hold any liquid chemical for the chemical treatment of the boilers. See attached picture

Description of Repairs Needed:

Labor and material to a.) replace Chemical Pot Feeder, Mechanical Room

Material List:

(1) CW-EC-2TC (2 gal feeder w legs, rated 300 psi)...\$

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
7	\$1,014.04	\$396.36	\$1,410.40