



Date: 4/25/2023

Region: 4C
FAC ID: WV014

CSS No.: 92837
Maximo Work Order No.: 12538

Asset #: G243

Original Work Request:

The rope on the flag pole broke during the windstorm.

Description of Repairs Needed:

Labor and material to a.) rent a lift to replace the rope for the flag b.) return the flag back to the pole and will coordinate with the unit for further instruction on where they would like the flag placed.

Material List:

(1) 5/16 inch PH8 White Rope (500 ft)

Equipment List:

Lift

PM WO History:

11789

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
6	\$771.34	\$765.46	\$1,536.80