



Date: 4/20/2023

Region: 4A
FAC ID: NY070

CSS No.: 93028
Maximo Work Order No.: 12568

Asset #: 4855

Original Work Request:

Repair piping fill glycol tank.

Description of Repairs Needed:

Labor and material to a.) Supply and add up to 55 gallons of 40% glycol b.) Pressurize system to normal operating pressure c.) Refill auto feed glycol tank d.) Check chilled water expansion tank pressure, adjust as needed e.) Leave extra glycol on site

Material List:

55 Gallons of 40% Glycol

Equipment List:

NA

PM WO History:

12206

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
24	\$2,824.05	\$1,091.41	\$3,915.46