



Date: 5/26/2023

Region: 4A
FAC ID: NY126

CSS No.: 93110
Maximo Work Order No.: 12584

Asset #: NA

Original Work Request:

Repair circulating pump. Chilled water pump 1B is making loud noise while running.

Description of Repairs Needed:

Labor and material to a.) shut down and drain the piping disconnect the wiring b.) remove the existing pump with bad bearings c.) install the new pump rewire d.) recharge the system and test for proper operation

Material List:

(1) #END SUCTION PUMP PER SPEC TACFI2009D
(S3475450)

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
6	\$900.00	\$7,376.10	\$8,276.10

