



Date: 4/25/2023

Region: 4A

FAC ID: NY030

CSS No.: 93111

Maximo Work Order No.: 12585

Asset #: 6572

Original Work Request:

Repair Boiler #1 Boiler #1 is in alarm with ignition failure

Description of Repairs Needed:

Labor and material to a.) Lock out tag out electric and natural gas service. b.) Remove and replace failed gas valve. c.) Check boiler and piping for natural gas leaks. d.) Perform start up on the boiler and adjust as required.

Material List:

(1) Gas Valve DUNGS
TYP: DMV-SE 512/11 S22

Equipment List:

NA

PM WO History:

11088

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
11	\$1,522.33	\$5,175.40	\$6,697.73