



Date: 4/25/2023

Region: 4A
FAC ID: NY010

CSS No.: 93227
Maximo Work Order No.: 12763

Asset #: G083

Original Work Request:

Repair the flagpole rope as it has broken completely off the flagpole and the Flag cannot be raised

Description of Repairs Needed:

Labor and material to a.) restrung the internal winch flagpole WCA-0400 1/8 stainless steel cable assembly

Please note: We will need to wait until the ground is firm enough to drive our bucket truck on to do the repair.

Material List:

(1) WCA-0400 1/8 stainless steel cable assembly

Equipment List:

Bucket Truck

PM WO History:

11732

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
7	\$930.94	\$871.21	\$1,802.15