



Date: 5/26/2023

Region: 4C
FAC ID: WV046

CSS No.: 93599
Maximo Work Order No.: 13007

Asset #: NA

Original Work Request:

Repair by replacing 4 CO detectors that are causing the Fire alarm panel to be in trouble alarm.

Description of Repairs Needed:

Labor and material to a.) replace (4) OOHC Smoke, Heat and CO Detectors

Material List:

OOHC Smoke, Heat and CO Detectors

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
4	\$576.00	\$720.00	\$1,296.00