

Facility Repair Proposal

Region: 4A
Fac ID: PA063
Date: 11/10/2022

CSS # 90715
Maximo Work Order No.: 11312

Asset ID: NA

Original Work Request:
Replace the burner tube assembly for boiler #2.

Description of Repairs Needed:
Following investigation, it has been determined that the burner tube assembly for boiler #2 has a crack in it and requires replacement. Labor and materials to make necessary repairs to boiler #2.

Parts List:

- Burner List (HTP 7350P-031)
- Spark Electrode (HTP 7350P-020)
- Flame Rectification Probe (HTP 7350P-022)
- Gaskets

Equipment List:
NA

PM History:
NA

Cost Proposal:
See attached RS Means Estimate.

Total Cost: \$4665.83

