



Facility Repair Proposal

Region: 4C
Fac ID: VA012
Date: 12/12/22

CSS # 90816
Maximo Work Order No.: 11476

Asset ID: NA

Original Work Request:

Air Vents need to be replaced and system purged before boilers have the annual PM done

Description of Repairs Needed:

Labor to a.) diagnose the heating loop system, the is air locked.

Parts List: NA

Equipment List: NA

PM History:

NA

Cost Proposal:

See attached RS Means Estimate.

Total Cost: \$934.80

Estimate Name: CSS 90816 - WO 11476 - VA012 Replace Vent and Purge Air out of Boiler Loop

ESTIMATE INFORMATION

Client Name: **Type:** Unit **Notes:**
Estimate Address: 5746 Reserve Way, Dublin, VA 24084 **Measurement System:** US Standard

COST DATA

Estimate Summary:						Catalog: Facilities and Commercial Renovation	
						Format: MasterFormat 2018	
						Release: Year 2022 Quarter 4	
						Labor Type: Repair & Remodeling	
						City Cost Index: VIRGINIA / ROANOKE (240-241)	