

Service Items

Name	Description	Tier 1 Price	Unit Type	QTY	Taxable
Labor	See attached pages for details of work performed.	\$0.00	Hour	1	N

TOTAL*: **\$0.00**

* Not including taxes

Service Forms

Daily Form Fill out every day, even on PMs, and projects

TECH NAME Tom Timlin
DATE 12/13/22
TOOLS USED none
MATERIALS USED none
DESCRIPTION OF WORK PERFORMED Found the CO2 sensor in the motorpool they were having issues with. Got the information off of it and sent it in to get a quote on replacing it.
HOURS REGULAR:
OVERTIME:

Attachments

Title	File Name
12-13 Franklin mototpool CO2 sensor	12-13 Franklin mototpool CO2 sensor.pdf

Service Items

Name	Description	Tier 1 Price	Unit Type	QTY	Taxable
Labor	See attached pages for details of work performed.	\$0.00	Hour	1	N
TOTAL*:	\$0.00				

* Not including taxes

Service Forms


Daily Form Fill out every day, even on PMs, and projects

TECH NAME Tom Timlin
DATE 2/22/23
TOOLS USED hand tools
MATERIALS USED 1: CM-6 CO2 sensor
DESCRIPTION OF WORK PERFORMED Installed the New CO2 sensor in bay 1 of the garage. Wired it in so it got power from the local transformer. The new sensors will not connect to the old control system. But the new sensor has a buzzer built into it and will alarm them locally. I recommend having a control company come in and see if they can get into the old controller and reprogram the system to accept the sensor. Sensor is working properly at this time.


HOURS REGULAR:
OVERTIME:

Attachments

Title 20230222_095858
File Name 06322929-5e56-401e-a15a-c6e049c34d5d.jpg
02/22/2023 11:44 AM



20230222_095731
02/22/2023 11:44 AM
9aafc0ac-f8a4-44ef-a39e-dbf17cd8189c.jpg



CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: PA035 Date of Visit: 12/13/22

Contractor Personnel on Site:

1. Tom Timlin 2. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. _____

Service Calls – Service Call Number and Description

1. CSS# 91081. Got the information on the CO2 sensor in motorpool
2. CSS# _____
3. CSS# _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Thomas Timlin Date: 12/13/22

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, I certify that the above-named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed.
This is NOT a Certification that the Work was performed correctly – The COW simply verifies that that someone representing the Contractor was onsite and accomplished something

Print Name/Rank: Cynthia Croyle/ AFOS Date: 12/13/22

Signed: 

E-Mail: cynthia.a.croyle.ctr@army.mil

CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: PA035 Date of Visit: 2/22/23

Contractor Personnel on Site:

1. Tom Timlin 2. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. _____


Service Calls – Service Call Number and Description

1. CSS# 91081. C02 sensor for garage
2. CSS# _____
3. CSS# _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Thomas Timlin Date: 2/22/23

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, I certify that the above-named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed.
This is NOT a Certification that the Work was performed correctly – The COW simply verifies that that someone representing the Contractor was onsite and accomplished something

Print Name/Rank: Cynthia Croyle/ AFOS Date: 2/22/23

Signed: 

E-Mail: cynthia.a.croyle.ctr@army.mil