



## CUSTOMER QUOTATION NO. 585

CMI Management, Inc.  
5285 Shawnee Road Suite #510  
Alexandria VA 22312

**Quote Name:** 14140  
**Quote No:** 585  
**Site:** MD066 Fox Tail Avenue  
**Site Contact:**  
**Salesperson:** Lindsay Ruby  
**Created Date:** 04/26/2021  
**Valid For:** 30 Day(s)

**WO#:** 14140

**CSS Ticket Number:** 30139

**Problem:** CHEM line is broke to the cooling tower.

S&S proposes to install a new heat trace cabling for cooling tower chemical treatment feed that will replace faulty cabling that caused the pipe to melt (piping already repaired); splice into existing heat trace, secure pipe and reinstall insulation and pipe covering.

### Service

| Item                 | Quantity | Unit Price              | Total      |
|----------------------|----------|-------------------------|------------|
| 24ft 120v heat trace | 1.00     | \$155.46                | \$155.46   |
| Splice Kit           | 1.00     | \$35.35                 | \$35.35    |
| Diagnosis Fee        | 1        | \$783.87                | \$783.87   |
| Plumbing Labor Rate  | 8        | \$100.00                | \$800.00   |
|                      |          | <b>Sub-Total ex Tax</b> | \$1,774.68 |
|                      |          | <b>Tax</b>              | \$0.00     |
|                      |          | <b>Total inc Tax</b>    | \$1,774.68 |

|                         |            |
|-------------------------|------------|
| <b>Labor</b>            | \$1,583.87 |
| <b>Materials</b>        | \$190.81   |
| <b>Sub-Total ex Tax</b> | \$1,774.68 |
| <b>Tax</b>              | \$0.00     |
| <b>Total inc Tax</b>    | \$1,774.68 |