

**CERTIFICATION OF WORK
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY126 Date of Visit: 6-7-24

Contractor Personnel on Site:

- | | |
|------------------------|----------|
| 1. <u>CHARLES DOWD</u> | 4. _____ |
| 2. _____ | 5. _____ |
| 3. _____ | 6. _____ |

Service Call Number

CSS# 97164 WO# 15245

Description of Repairs

REESTABLISH CONNECTION BETWEEN OMS & TB JAEUS

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: CHARLES DOWD Date: 6-7-24

Signed: 

To be signed by Facility Manager:


By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: John F. Granata Date: 06/12/2024

Signed: 

E-Mail: john.f.granata.ctr@army.mil

JOB NAME: CHILI V542C
ADDRESS:
DATE: 6-7-24
JOB #:
CUST. PO#:
CALL TYPE: T&M ☐ QUOTE ☒ PM ☐



GREATER NIAGARA



Mechanical, Inc.

Phone: 716.695.3600 ∞ Fax: 716.695.3700

TROUBLESHOOTING OMS CONNECTION TO TRAINING BUILDING. (44)
TO UPDATE POINT REFERENCES IN TIS JAEV, OMS ~~THE~~ JAEV MUST
HAVE BEEN RENAMED. ALL POINTS AND CONTROL RESTORED

*** NOTE FOR SERVICE *** MINISPLITS IN 151 IT ROOM RAISED ON CODE PG
 *** PUMP 1A CITS UPS DOWN *** CRUI IN OMS NOT RUNNING
 *** FLOW STATUS NOT WORKING IN TB CITS LOOP PUMPS
 *** LEAKING GLYCOL IN OMS NIGHTM XTR EVAP IN OMS BLUE RM CYCLING
 DUE TO COLD AIR FROM MINISPLIT *** FLOW STATUS IN OMS ITWS NOT WORKING

[illegible]

| | |
|-----------------|--|
| *SERVICE CHARGE | |
| SUB TOTAL | |
| TAX | |
| TOTAL | |

*Service charge covers expense of truck, tools, and sundries.