

**New England Mechanical**4 Airport Boulevard  
Latham, NY 12110P: (518) 782-5011  
F: (518) 782-5013[www.nemsi.com](http://www.nemsi.com) AA / EOE**Our Other Locations:**

\*Pawtucket, RI \*Waterford, CT  
\*Manchester, NH \*Palmer, MA  
\*South Windsor, CT \*Trumbull, CT

**SERVICE ORDER#**  
**161007288**

Page 1 of 1

<b>Location</b>	Army Reserve-1201 Hillside Ave	<b>Service Rpt #</b>	1388664	<b>Agreement / Type</b>	
<b>Address</b>	1201 Hillside Ave	<b>Service Date</b>	01/18/23	<b>Technician</b>	Dennis Daley
<b>City</b>	Schenectady	<b>Customer #</b>	1018955	<b>Skill Level</b>	
<b>State</b>	NY	<b>Customer PO</b>	21044	<b>Union</b>	
<b>Contact</b>	<b>Zip</b>	<b>Cust Phone</b>		<b>Service Complete</b>	N
		<b>Sales Rep</b>		<b>Visit Complete</b>	Y

<b>Problem Description:</b>	NH(No Heating) NO HEAT in OMS Offices.
-----------------------------	--

<b>Visit Resolution:</b>	Trane furnace - tripped on flame failure, checked operation and found burners not lighting. Checked hot surface igniter, checked volts to gas valve. Checked gas pressure. Found gas valve stuck closed but turned on during testing. Gas valve should be replaced. Need to quote new gas valve.
--------------------------	--


<b>XOi Customer Share Link:</b>	<a href="https://visionshare.xoi.io/?id=XA-F2BC-438F4BAE791E4829A2A40199185DA737">https://visionshare.xoi.io/?id=XA-F2BC-438F4BAE791E4829A2A40199185DA737</a>
---------------------------------	---

LABOR				
Hours	Billable	Agreement/Nonbillable	Type (Internal Use)	
Regular	2.00	0.00	NAB	

Allocation of charges is subject to change based on management review of the actual agreement coverage if applicable.

**ASSETS SERVICED**

Client Ref.	Asset ID	Asset Description	Manufacturer	Model / Serial No.
	1006	Furnace	Trane	TUB1B060A9361AB / 13201H461G

Visit Approved By:	
--------------------	--

Signed By: Mike Moseman

Date: 01-18-2023 Time: 15:59