

**CERTIFICATION OF WORK  
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY051 Date of Visit: 6/15/23

Contractor Personnel on Site:

- |                     |          |
|---------------------|----------|
| 1. <u>Hydestone</u> | 4. _____ |
| 2. _____            | 5. _____ |
| 3. _____            | 6. _____ |

**Service Call Number**

CSS# 92370 WO# 21471

**Description of Repairs**

\_\_\_\_\_  
Labor and materials to a.) to replace (2) Belimo zone actuators (valves 56 and 62) and b.) (1) circuit setter (valve 61) located at or near room 108. This quote covers the shutdown of the boiler system, removal and replacement of the identified valves, and the startup and testing of the boiler system  
\_\_\_\_\_  
\_\_\_\_\_

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: Karlee Demain Date: 6/16/23

Signed: Karlee Demain

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Noah Ingerson / AFOS Date: 6/20/2023

Signed: Noah Ingerson

E-Mail: noah.l.ingerson.ctr@army.mil