

**CERTIFICATION OF WORK
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY051 Date of Visit: 7/6/23

Contractor Personnel on Site:

1. <u>Andy Hunold</u>	4. _____
2. _____	5. _____
3. _____	6. _____

Service Call Number

CSS# 93545 WO# 22698

Description of Repairs

Labor and material to repair the hot water supply line in ceiling.

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Karlee Demain Date: 7/6/23

Signed: Karlee Demain

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Noah Ingerson / AFOS Date: 7/6/2023

Signed: Noah Ingerson

E-Mail: _____