

## CERTIFICATION OF WORK SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY051 Date of Visit: 7/26/23

Contractor Personnel on Site:

1. <u>Hydestone</u>	4. _____
2. _____	5. _____
3. _____	6. _____

**Service Call Number**

CSS# 93709 WO# 22715

**Description of Repairs**

Labor and material to a.) new Belimo actuator serving room 115. b.) Isolate the valve and remove the existing one c.) install the new valve. d.) pressure test and perform a system check to insure it is operating to all manufacturer specifications

---

---

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Karlee Demain Date: 7/26/23

Signed: Karlee Demain

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Noah Ingerson / AFOS Date: \_\_\_\_\_

Signed: Noah Ingerson

E-Mail: \_\_\_\_\_



**BELIMO**  
Assembled in USA  
**LRB24-3-T**  
LRX24-3-T (default)  
4001  
45 in-lb / 5 Nm  
AC/DC 24 V 50/60 Hz  
90°  
2.0 VA 1.5 W

2023-04-26

X1  
Y2  
NEMA1

ZP  
Enclosure Type 1  
Class 2 Supply  
T.I. & R.E.  
LISTED C UL US  
9405



BEUMO

B209

1/2" Cv 0.8

2023-05-30