

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 9-6-23

ARRIVAL TIME 6:00

DEPARTURE TIME 5:00

JOB/TCK. NO. 197930

CUSTOMER P.O. NO. CSS# 94005

JOB NAME/LOCATION USARC - Galax VA033

SERVICE REQUESTED (24) Investment is to replace the Compressor, contactor, liquid line drier, wiring harness, and recharge Trane

Manufacturer: TraneModel#: TTA180H300AASerial#: 16245WYWTA

Refrigerant Added: Qty lb oz TYPE

Refrigerant Removed: Qty lb oz TYPE

WORK PERFORMED/UNIT INFO.

Picked up Eli at Tamarack and drove to Galax and checked in and he started getting old compressor out while I went to roof and started work on the air handler had to remove bad contactor and overlaod block and had to replace bad phase monitor and fan status ct and set it up. Then helped with get new compressor in and leak checked system all was fine then put on vac pump and let it pull down to 450 microns and the charged unit with 16LBS of 410A and checked charging chart and all looked fine cleaned up work area and put tools back on van and went back inside and made sure that bldg. was cooling down all was good.

 Leak Tested Leak Found Leak Repaired

Method: _____

Total Charge: _____

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

QTY.	PART NO.	DESCRIPTION	P.L.	VENDOR	
1		Shipping & Handling		Kele	232239
1		RiBXGTA TRANSFORMER		Kele	232239
1		Shipping & Handling		United	232238
1		ICM450C PHASE MONITOR		United	232238
1		Shipping & Handling		Trane	232237
1		RLY03191		Trane	232237
1		SFCTR3P40A24VL		Trane	232237
1		WIR06693		Trane	232237
1		DHY01470		Trane	232237
1		CTR02006		Trane	232237

SUMMARY OF TIME

SERVICE TECHNICIAN	ON SITE REG.	ON SITE O.T.	REG. TRAVEL	O.T. TRAVEL	TOTAL HRS.	MEALS	LODGING	TOLLS	MILES	OTHER
58 Mark Bass	8	3			11					
1346 Eli Ayers	8	3			11					

JOB COMPLETE

YES X NO _____ EXPLAIN _____

SIGNATURE _____



Customer Representative

