

## **CERTIFICATION OF WORK SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY067 BLDG2 Date of Visit: 11/3/22

#### Contractor Personnel on Site:

1. Patrick Brown 4. \_\_\_\_\_  
2. \_\_\_\_\_ 5. \_\_\_\_\_  
3. \_\_\_\_\_ 6. \_\_\_\_\_

## Service Call Number

CSS# 90457 WO# 19751


## Description of Repairs

I rebuilt the flush valve with a 3.5 gallon per flush Sloan rebuild kit and tested for proper operation

## **CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: Patrick Brown Date: 11/3/22

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: THOMAS, AL SFC Date: 11/3/22

Signed: 

E-Mail: A.J.Thomas1.mil@Army.mil



