

## **CERTIFICATION OF WORK SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY067 BLDG1 Date of Visit: 5/9/23

#### Contractor Personnel on Site:

1. Patrick Brown 4. \_\_\_\_\_  
2. \_\_\_\_\_ 5. \_\_\_\_\_  
3. \_\_\_\_\_ 6. \_\_\_\_\_

## Service Call Number

WO# 22135 WO# 22135

## Description of Repairs

Labor and material to check the controller valve above the ceiling for leaks, wipe down the equipment and replace the ceiling tile

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: **Patrick Brown** Date: **5/9/23**

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Casimir Szatkowski/65-09 Date: 5/9/23

Signed: John

E-Mail: \_\_\_\_\_



