



Work Order  
No: 57288

Armistead Mechanical Inc. Services  
168 Hopper Avenue, Waldwick NJ 07463

Date: 12/3/2021  
Status: Schedule

<b>Service To:</b> SGT Catalin D Dima AFRC <b>Address:</b> 910 Raz Avenue New Windsor NY 12553	<b>Contact:</b> <b>Phone:</b>
--	----------------------------------

#### Work Summary

Repair water heater gauge in room 114

#### Equipment

ID	Description	Type	Make	Model	Serial Number	Location	Year Installed
----	-------------	------	------	-------	---------------	----------	----------------

#### Labor

Date	Technician	Hours
11/30/2021	20014 (David J. Hinnrichs)	1.00
12/3/2021	20014 (David J. Hinnrichs)	1.00

#### Parts

Description	Quantity
-------------	----------

#### Notes

Topic	Note
WORK ORDER NOTES	11/30 DH located broken thermometer on #3 heater. Noted brand and style. Picked up new at supply house. Must return to install 12/3 DH. Install thermometer. Old stem corroded in well

<b>Customer Signature</b>		<b>Signed By</b>		<b>Date</b>	
---------------------------	--	------------------	--	-------------	--