



Proudly serving the entire states of Virginia & North Carolina.

Altavista, VA • Charlottesville, VA • Chesapeake, VA • Christiansburg, VA

Falmouth, VA • Lynchburg, VA • Richmond, VA • Greensboro, NC

P.O. Box 119 • Altavista, VA • 800.789.7199 • service@mooreelectric.com

Billing Address	Site Address
Customer: INTERNATIONAL SUPPORT GROUP Address: 9000 SHERIDAN ST Phone: PEMBROKE PINES FL 33024 954-900-1095	Customer: ISA USARC VA049 CHESTERFIELD Address: 6700 STRATHMORE ROAD Phone: NORTH CHESTERFIELD VA 23237 8045855211
Service Call #: COM0098429	Call Type: COM-PLMB

Service Requested

PO 15477 QUOTE APPROVAL 987.72 / 6 HRS

DESCRIPTION OF EQUIPMENT:

Sewer Drain

DESCRIPTION OF PROBLEM:

Pipe is damaged, customer requesting quote to camera line, locate deficiency and quote definitive repairs

DESCRIPTION OF REPAIRS:

Moore's will drive to site, pull toilet and camera line. Will use locator to find depth of pipe in ground for repair quote purposes. Will reset toilet and clean up site. Video footage will be provided to show deficiency. Additional quote will be necessary for definitive repair. **this quote is site un-seen

Problems

Description	Tech	Equip. Desc and Model	Manufacturer	Equip. Serial	Asset ID
Camera Sewer	CORYSANDLI				

Tech Notes

Tech: CORY SANDLIN, Date: 1/4/19 6:57 PM - Arrived on site. Checked in with the visitors office. Met Troy at site. Pulled toilet in men's room to camera line to see if the sink drain line connection could be seen. Found that the toilet in the men's and women's room are on a cross. The drain for the sinks are upstream of the toilet connections. Was not able to get camera into main due to the cross. Drained sinks in men and women's room. Capped the drain line for the sink in the men's room. Ran a hose from the janitors closet with a drain king. Put drain king in drain line for women's sink drain. Turned on utility sink in janitors closet and let the drain king run down the drain. The drain seemed to have cleared when using drain king. Reinstalled all parts to both men's and women's room sink. Tested the drain. The drain was still clogged. Drained water out of the drain. Poured liquid drain cleaner down line and let sit for 15-20 minutes. Rinsed the drain with hot water. Drain did not clear. The only option at this time to fix drain is to open wall and look at condition of drain and rework drain inside wall to allow it to be cleared in the future.

Signed By	Verbal	Signature		Date	1/4/2019
-----------	--------	-----------	---	------	----------