

Service Items

Name	Description	Tier 1 Price	Unit Type	QTY	Taxable
Labor	See attached pages for details of work performed.	\$0.00	Hour	1	N
TOTAL*:	\$0.00				

* Not including taxes

Service Forms

Daily Form Fill out every day, even on PMs, and projects

TECH NAME Tom Timlin

DATE 6/26/23

POINT OF CONTACT: Reginald

DESCRIPTION OF WORK PERFORMED Had the water company come out and shut the water off at the street. Once it was off, we drained water from the building and removed the first valve in line. Once out, we cleaned the old flanges up and installed the new one with new gaskets. Tightened everything down. Called the water company back out, and they turned the water on. Checked for leaks, and everything was dry at this time.

TOOLS USED hand tools

MATERIALS USED OR PICTURE OF TAG* 1: 3" gate valve (ordered)
3: 3" gaskets


HOURS REGULAR:

OVERTIME:

Attachments

Title File Name

20230626_102932
06/26/2023 02:15 PM 2c9d052b-32ad-4008-ba90-b1bd3a39ce17.jpg




20230626_090359
06/26/2023 02:15 PM

dc1becfe-4b57-4346-83c4-6c495b7ff269.jpg




20230626_085653
06/26/2023 02:15 PM

bd1f7b94-d538-4052-88fb-b6ab2e2249dc.jpg



20230626_085704
06/26/2023 02:15 PM

ca5fd491-ba40-4419-b8f9-247696b53d96.jpg



6-26-23 Water main
valve replacement

6-26-23 Water main valve replacement.pdf

CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: PA062 Date of Visit: 6/26/23

Contractor Personnel on Site:

1. Tom Timlin 2. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. _____


Service Calls – Service Call Number and Description

1. CSS# 93578. Replacement of the first water main valve
2. CSS# _____
3. CSS# _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Tom Timlin Date: 6/26/23

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, I certify that the above-named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed.
This is NOT a Certification that the Work was performed correctly – The COW simply verifies that someone representing the Contractor was onsite and accomplished something

Print Name/Rank: Rebecca Dithrich, GS-09 Date: 6/26/23

Signed: 

E-Mail: rebecca.l.dithrich.civ@army.mil