

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 03/03/2023 ARRIVAL TIME 9:30 DEPARTURE TIME 12:00 JOB/TCK NO 194249

DEPARTURE TIME 12:00 JOB/TCK. NO. 194249

JOB/TCK. NO. 194249

CUSTOMER PO. NO. CSS# 90111

JOB NAME/LOCATION USARC - Rainelle WV034

SERVICE REQUESTED Replace release valve on Apex boiler 4. POC Reg Cook
703-738-5307

Manufacture:			
Model#:			
Serial#:			
Refrigerant Added:	Qty	lb	oz
Refrigerant Removed:	Qty	lb	oz

- Leak Tested**
- Leak Found**
- Leak Repaired**

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO

Got on site and checked in with customer. Went to the boiler room and located boiler #4. Tested the boiler relief valve and found water squirting out of the top of the valve. Got the info off of the valve and filled out work completion form. Sent in a quote to replace the valve, and let Reg know everything. Filled out paperwork after that and then left.

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

SUMMARY OF TIME

JOB COMPLETE YES NO EXPLAIN

SIGNATURE _____

Customer Representative