

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 2/20/2024 ARRIVAL TIME 8:00am DEPARTURE TIME 4:00pm JOB/TCK NO 203703

CUSTOMER P.O. NO. _____

JOB NAME/LOCATION USARC - Cross Lanes WV006

SERVICE REQUESTED (16) *Investment is to replace the vertical HW Expansion Tank with a horizontal HW Expansion Tank.*

Manufacture:			
Model#:			
Serial#:			
Refrigerant Added:	Qty	lb	oz
Refrigerant Removed:	Qty	lb	oz

- Leak Tested**
- Leak Found**
- Leak Repaired**

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO

Checked in and shut boilers and pumps down. Removed old expansion tank and installed new tank and reran glycol feeder lines. Then repiped pop offs and started boilers and pumps. We then cleaned up and added glycol to the feeder tank. We tested boiler to 180 degrees with no pop offs going off. We then checked out.

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

SUMMARY OF TIME

JOB COMPLETE YES NO EXPLAIN _____

SIGNATURE _____

Customer Representative