

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 5-13-24 ARRIVAL TIME 7:00 DEPARTURE TIME 10:30 JOB/TCK NO 206252

DEPARTURE TIME 10:30 JOB/TCK. NO. 206252

JOB/TCK. NO. 206252

CUSTOMER PO. NO. CSS#97018

JOB NAME/LOCATION *USARC - Beaver WV002*

SERVICE REQUESTED (20) Investment is to replace the TXV on York AHU-2 (M# CS74SHFC; S# GECM-001804)

Manufacturer: Trane
Model#: TTA180B300BA
Serial#: J16198468

Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

Leak Tested
 Leak Found
 Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO

Arrived on site, checked in with customer. Set up ladder and took all the tools i needed to do the job. Took panels off and seen that the disconnect was already turned off. It was on the last time i was here trouble shooting the unit before. I then hooked up gauges and found that the king valve was so rusted up that you could not turn it. I then look at the pressures and it only had 30 psi on it and the unit was r-22. I then took panel off the other circuit and that side was flat on gas. I then climbed down and went and told client that the unit was in really bad shape and that it probably was not cost effective for me to repair it and should probably go ahead and replace the unit. Should client the pictures i took and they said to write it up for them. I went and took

NATURE OF WORK

Regular Service _____
Quoted Service _____
Start-up/Warranty _____
SPD _____
Contract Service _____
Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

SUMMARY OF TIME

JOB COMPLETE YES NO EXPLAIN

SIGNATURE _____

Customer Representative

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE ARRIVAL TIME 10:05 am DEPARTURE TIME JOB/TICK NO 206252

CUSTOMER PO. NO. CSS#97018

JOB NAME/LOCATION USARC - Beaver WV002

SERVICE REQUESTED

Manufacturer: Trane
Model#: TTA180B300BA
Serial#: J16198468

Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

- Leak Tested**
- Leak Found**
- Leak Repaired**

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO

WINTER CHILDBORN INC. pictures and then packed up all my tools and put them away and done paperwork.

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

SUMMARY OF TIME

JOB COMPLETE

YES _____ NO _____ EXPLAIN _____

SIGNATURE _____

Customer Representative