

5 Year Hydrostatic Fire Department Connection Test

v1.01

Location Code: USSNJAP

Contact: CINDY CROYLE

Contact Address: 7001 KLIER DR, BLDG 91714
FAIRVIEW, PA 16415-2468

Phone: 412-477-7816

Email: cynthia.a.croyle.ctr@army.mil,
reginald.cook@cmimgmt.com

Property Evaluated: USAR PA209 FAIRVIEW (Business)
7001 KLIER DR, BLDG 91714
FAIRVIEW, PA 16415-2468

Description: 5 Year FDC Hydro (Office 5/yr FDC
Hydro 8/24)

Work Order: SV2407220405/1

Company: GRUNAU COMPANY

Address: 590 E WESTERN RESERVE RD, BLDG
5
BOARDMAN, OH 44514

Company Phone: 330-758-3500

Inspector: BRAD COGSWELL
OH FIRE - 54.89.5329

Date of Work: 8/1/2024

Deficiency Summary

There are no reported deficiencies for this submission

General Comments

These items are outside the regular scope of the required inspection and are not the result of an engineering review. This information is not intended to be all-inclusive but rather a list of items discovered as a by-product of the required inspection.

There are no general comments for this submission

5 Year Hydrostatic Fire Department Connection Test

v1.01

1. General

Property:

USAR PA209 FAIRVIEW

Address:

7001 KLIER DR, BLDG 91714, FAIRVIEW, PA, 16415-2468

Test Description:

Sprinkler

Test Type:

NFPA 25 5th Year

If 'Other', please describe

Inspected By:

BRAD COGSWELL

Date of Work

8/1/2024

2. Information

Information			
Siamese Location	On building	Plugs or Caps Installed?	Yes
Siamese Type	Swivel Collar	Proper Signage Installed	Yes
Siamese Size	4"	Water Source	Backflo device
Check Valve Location	At valve	Water Source Distance	15'
Check Valve Height	3'	Power Source	N/A
Check Valve Size	4"	Valve Shutoff Location	At riser
Check Valve Type	Grooved	Swivel Condition	Good
Ball Drip Size	.5"		

3. Hydrostatic Test

Hydrostatic Test Details	
Start Time	9:00 a.m
Initial Pressure	150 psi
Stop Time	11:00 a.m
Final Pressure	145 psi

4. Reverse Flow Details

Reverse Flow Details	
Reverse Flow Performed	Swival adapter connected
Shutoff Valve Location	At valve
Draining Procedure	Ballvalve installed
Testing Procedure	Grooved removed and flipped?
Spool Piece Length	10'
Clapper Pipe Size Needed	N/a

5. Test Result

Pass Fail

6. Comments

7. Inspector Signature

Signature of Inspector:

Inspector License:



OH FIRE - 54.89.5329

