

## SERVICE REPORT

DATE 2024 6 18 ARRIVAL TIME 800 DEPARTURE TIME 1200 JOB/TCK. NO. 209649

CUSTOMER P.O. NO. \_\_\_\_\_

**JOB NAME/LOCATION** *USARC - South Ridge WV007*

**SERVICE REQUESTED** (6) Investment is to Charge Trane Chiller (M# CGAM080A; S# U15B47125) that serves the CW System. NTE

Manufacture: <i>Trane</i>				
Model#: <i>CGAM080A2L02AXD2A1A1A1AX</i>				
Serial#: <i>U15B47125</i>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: \_\_\_\_\_

Total Charge: \_\_\_\_\_

**WORK PERFORMED/UNIT INFO.**

Arrived on site, checked in with customer. Started up chiller top off charge running 18 subcooling exv is at 55% full load both circuits running same

### NATURE OF WORK

Regular Service \_\_\_\_\_  
Quoted Service \_\_\_\_\_  
Start-up/Warranty \_\_\_\_\_  
SPD \_\_\_\_\_  
Contract Service \_\_\_\_\_  
Energy Management \_\_\_\_\_

#### PARTS, MATERIALS AND SUBCONTRACTED SERVICES

[illegible]

### SUMMARY OF TIME

[illegible]

JOB COMPLETE YES X NO \_\_\_\_\_ EXPLAIN \_\_\_\_\_

**SIGNATURE** \_\_\_\_\_

**Customer Representative**