

CASTO TECHNICAL SERVICES, INC.

## SERVICE REPORT

DATE 2025 5 20 ARRIVAL TIME 7:30

DEPARTURE TIME 9:30

JOB/TICK NO 221407

CUSTOMER PO. NO. FEMS31562

JOB NAME/LOCATION USARC - Cross Lanes WV006

**SERVICE REQUESTED** Repair 2 A/C units in the Marines Vault and 2 units in the Marines Supply that are not working. Once there 1.5hrs call

Manufacture: _____
Model#: _____
Serial#: _____
Refrigerant Added:      Qty      lb      oz      TYPE
Refrigerant Removed:      Qty      lb      oz      TYPE

- Leak Tested**
- Leak Found**
- Leak Repaired**

**Method:** \_\_\_\_\_

**Total Charge:** \_\_\_\_\_

**WORK PERFORMED/UNIT INFO**

Checked in with customer. Then got information off split systems to quote or replace. Cu-3 has bad compressor, condenser fan and capacitor. Cu-1 has bad condenser fan and capacitor.

**NATURE OF WORK**

Regular Service \_\_\_\_\_

Quoted Service \_\_\_\_\_

Start-up/Warranty \_\_\_\_\_

SPD \_\_\_\_\_

Contract Service \_\_\_\_\_

Energy Management \_\_\_\_\_

#### **PARTS, MATERIALS AND SUBCONTRACTED SERVICES**

## **SUMMARY OF TIME**

**JOB COMPLETE**

YES X NO \_\_\_\_\_ EXPLAIN

**SIGNATURE** \_\_\_\_\_

### **Customer Representative**