

**CASTO TECHNICAL SERVICES, INC.**

**SERVICE REPORT**

DATE 2026 4 16 ARRIVAL TIME 8:00 DEPARTURE TIME 1:00 JOB/TCK. NO. 232930

CUSTOMER P.O. NO. \_\_\_\_\_

JOB NAME/LOCATION USARC - New River Valley Memorial VA012

SERVICE REQUESTED (21) Investment is to Recover the Refrigerant, replace the Compressor and Filter Drier, and Recharge CU (M#

- Leak Tested
- Leak Found
- Leak Repaired
- Method: \_\_\_\_\_
- Total Charge: \_\_\_\_\_

Manufacture: <u>Trane</u>				
Model#: <u>4TWR7036B1000DA</u>				
Serial#: <u>183737842F</u>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

**WORK PERFORMED/UNIT INFO.**

Arrived on site, checked in with customer. Went around to the unit and started hooking up the Recovery machine. While pulling the freon out of unit we took the fan off the top and I climbed down inside the unit and unhooked the electrical connections. Then wrapped up the sensors on the piping with rags and then soaked them with water. Once we got the gas pulled out we then unbrazed the compressor. Put the new one in place and then brazed up the piping. The pulled the filter drier off and installed a new one. Hooked up vacuum pump and pulled system down to 418 microns. Shut the valve and made sure it held. Charged the system back up with what gas we pulled out. Hooked up all the electrical connections and then put fan back on. Turned

NATURE OF WORK	
Regular Service	_____
Quoted Service	_____
Start-up/Warranty	_____
SPD	_____
Contract Service	_____
Energy Management	_____

**PARTS, MATERIALS AND SUBCONTRACTED SERVICES**

QTY.	PART NO.	DESCRIPTION	P.L.	VENDOR	
1		Shipping & Handling		Trane	264116
1		DHY01452 FILTER DRIER		Trane	264116
1		Com14877 COMPRESSOR		Trane	264116

**SUMMARY OF TIME**

SERVICE TECHNICIAN	ON SITE REG.	ON SITE O.T.	REG. TRAVEL	O.T. TRAVEL	TOTAL HRS.	MEALS	LODGING	TOLLS	MILES	OTHER
1154 Shawn Shelton	5		3		8					
1468 Jeff Davis	6.50		1.50		8					

JOB COMPLETE YES X NO \_\_\_\_\_ EXPLAIN \_\_\_\_\_

SIGNATURE \_\_\_\_\_  
Customer Representative

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE \_\_\_\_\_ ARRIVAL TIME 12:20 pm DEPARTURE TIME \_\_\_\_\_ JOB/TCK. NO. 232930

CUSTOMER P.O. NO. \_\_\_\_\_

JOB NAME/LOCATION USARC - New River Valley Memorial VA012  
 SERVICE REQUESTED 4TWR7036B; S# 183737842F) located in the OMS Shop.

Manufacture: <u>Trane</u>				
Model#: <u>4TWR7036B1000DA</u>				
Serial#: <u>183737842F</u>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

Leak Tested

Leak Found

Leak Repaired

Method: \_\_\_\_\_

Total Charge: \_\_\_\_\_

WORK PERFORMED/UNIT INFO.

*unit on and tested pressures and made sure everything was running right. Made sure that the space was cooling off and then told client we were done. Cleaned up mess and told then done paper work.*

**NATURE OF WORK**

Regular Service \_\_\_\_\_

Quoted Service \_\_\_\_\_

Start-up/Warranty \_\_\_\_\_

SPD \_\_\_\_\_

Contract Service \_\_\_\_\_

Energy Management \_\_\_\_\_

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

QTY.	PART NO.	DESCRIPTION	P.L.	VENDOR

SUMMARY OF TIME

SERVICE TECHNICIAN	ON SITE REG.	ON SITE O.T.	REG. TRAVEL	O.T. TRAVEL	TOTAL HRS.	MEALS	LODGING	TOLLS	MILES	OTHER

JOB COMPLETE YES \_\_\_\_\_ NO \_\_\_\_\_ EXPLAIN \_\_\_\_\_

SIGNATURE \_\_\_\_\_  
 Customer Representative