

## SERVICE REPORT

DATE 2024 8 21 ARRIVAL TIME 7am DEPARTURE TIME 8am JOB/TCK. NO. 212215

CUSTOMER P.O. NO. WO16602/CSS98841

**JOB NAME/LOCATION** *USARC - Cross Lanes WV006*

**SERVICE REQUESTED** (64) Investment is to repair the Glycol Leak on the Piping.

Manufacture: _____				
Model#: _____				
Serial#: _____				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: \_\_\_\_\_

Total Charge: \_\_\_\_\_

**WORK PERFORMED/UNIT INFO.**

*Loaded and delivered glycol containers to job site.*

**NATURE OF WORK**

Regular Service \_\_\_\_\_

Quoted Service \_\_\_\_\_

Start-up/Warranty \_\_\_\_\_

SPD \_\_\_\_\_

Contract Service \_\_\_\_\_

Energy Management \_\_\_\_\_

#### PARTS, MATERIALS AND SUBCONTRACTED SERVICES

[illegible]

### SUMMARY OF TIME

[illegible]

JOB COMPLETE YES \_\_\_\_\_ NO \_\_\_\_\_ EXPLAIN \_\_\_\_\_

**SIGNATURE** \_\_\_\_\_

Customer Representative