

CASTO TECHNICAL SERVICES, INC.

## SERVICE REPORT

DATE 2025 6 11 ARRIVAL TIME 7:30

DEPARTURE TIME 4:00

JOBTICK NO 218742

CUSTOMER PO. NO. *PO-00012170*

JOB NAME/LOCATION USARC - Galaxy VA033

**SERVICE REQUESTED** (20) Investment is to replace the (3) Breakers that feed Lochinvar HW Heater #1 with (1) 100 AMP Breaker, and

Manufacturer: Lochinvar  
Model#: 100148485  
Serial#: 103135503

Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

- Leak Tested**
- Leak Found**
- Leak Repaired**

**Method:** \_\_\_\_\_

**Total Charge:** \_\_\_\_\_

**WORK PERFORMED/UNIT INFO**

got parts at warehouse dropped off in Fayetteville storage unit.

Arrived and went to boiler room and removed breaker panel cover and then removed the bad 20 amp breaker after cutting off power to panel and installed new 100 amp breaker and removed the wiring from the other two 20 amp breakers and removed the terminal block and hooked up wiring to disconnect from 100 amp breaker . Then had to rewire the hot water heater were it had been deratted by removing wiring to heater elements and check operation.

## NATURE OF WORK

**Regular Service** \_\_\_\_\_

**Quoted Service** \_\_\_\_\_

**Start-up/Warranty** \_\_\_\_\_

**SPD** \_\_\_\_\_

**Contract Service** \_\_\_\_\_

## Energy Management

#### **PARTS, MATERIALS AND SUBCONTRACTED SERVICES**

## **SUMMARY OF TIME**

**JOB COMPLETE**

YES  NO  EXPLAIN

**SIGNATURE**

### **Customer Representative**