

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 3-22-23 ARRIVAL TIME 7:30 DEPARTURE TIME 8:00 JOB/TCK. NO. 194249CUSTOMER P.O. NO. CSS# 90111JOB NAME/LOCATION USARC - Rainelle WV034SERVICE REQUESTED Replace PRV on Apex Boiler #4. POC Reg Cook 703-738-5307.
WO 12057.

Manufacture: <u>Apex</u>				
Model#: <u>APX500F-2L07</u>				
Serial#: <u>65271233</u>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

Arrived on site, checked in with customer. Went in and turned off pumps and valved off the boiler. Drained the water pressure off and then used pipe wrenches and took the pop off valve off the boiler. Then had to go to van and find a 3/4 inch coupling to put on it because the old one had female threads and the new one had male threads. Then i pipe doped all the threads and then put it all together. Then took pictures of the work and sent them in. Went through and turned all the valves open and turned pumps back on. Told client i was done and done paper work.

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

QTY.	PART NO.	DESCRIPTION	P.L.	VENDOR	
1		Shipping & Handling		Hvac	228739
1		10-301-10 Vavle		Hvac	228739

SUMMARY OF TIME

SERVICE TECHNICIAN	ON SITE REG.	ON SITE O.T.	REG. TRAVEL	O.T. TRAVEL	TOTAL HRS.	MEALS	LODGING	TOLLS	MILES	OTHER
1154 Shawn Shelton	1.50		1		2.50					

JOB COMPLETE YES X NO _____ EXPLAIN _____

SIGNATURE _____

Customer Representative