



# **INSPECTION CAPABILITIES**


---




**FIRE  
ALARM**



**FIRE  
SPRINKLER**



**FIRE ALARM  
MONITORING**



**FIRE  
SUPPRESSION**



**FIRE  
EXTINGUISHER**

---

**CONTACT US TODAY FOR A QUOTE**

Phone: 607-936-1500

Online: [davisulmer.com/rfq](http://davisulmer.com/rfq)

# Fire Alarm Supplementary Form



**Location Code:** VZSNUPV

**Contact:** Julie

**Contact Address:** 3126 LAKE RD  
HORSEHEADS, NY 14845-3103

**Phone:**

**Email:**

**Property Evaluated:** USAR-Horseheads (Assembly)  
3126 LAKE RD  
HORSEHEADS, NY 14845-3103

**Description:** Fire Alarm Supplement (New Device List)

**Work Order:** 0361500

**Company:** Davis Ulmer Sprinkler Co  
NYS Fire Alarm License 12000281635

**Address:** 55 Riverside Dr  
Corning, NY 14830

**Company Phone:** (607) 936-1500

**Inspector:** Justin Button  
N/A

**Date of Work:** 9/4/2025

## Deficiency Summary

There are no reported deficiencies for this submission

## General Comments

*These items are outside the regular scope of the required inspection and are not the result of an engineering review. This information is not intended to be all-inclusive but rather a list of items discovered as a by-product of the required inspection.*

There are no general comments for this submission



**Davis Ulmer Sprinkler Co**  
55 Riverside Dr  
Corning, NY 14830  
Phone: (607) 936-1500

## Fire Alarm Supplementary Form

Account Information				
Facility Name: USAR-Horseheads	Property Type: Assembly	Location Code: VZSNUPV		
Service Address: 3126 LAKE RD, HORSEHEADS, NY, 14845-3103				
Owner: Julie			Owner's Phone:	
Owner's Address: 3126 LAKE RD, HORSEHEADS, NY, 14845-3103				

Legend				
AS - Abort Station	BATT - Batteries	CoD - Carbon Monoxide Detector	CM - Control Module	DA - Damper
DD - Duct Detector	DH - Door Holder	EL - Emergency/Exit Light	FACP - Fire Alarm Control Panel	HD - Heat Detector
HORN - Horns	H/S - Horn-Strobes	LA - Low Air	MM - Monitor Module (Ansul, temp, CO, etc)	
MR - Manual Release	Other	PR - Phase Reversal	PS - Pull Station	PWS - Power Supply
SC - Signal/Sounder Control	SD - Smoke Detector	SD-Ion - Ion Smoke Detector	SD-Photo - Photo Smoke Detector	SPKR - Speakers
STROBE - Strobes	TS - Tamper Switch	WF - Waterflow		

Type	Total	Tested	Not Tested	Passed	Failed
● DD	4	4	0	4	0
■ PS	22	22	0	22	0
■ WF	1	1	0	1	0

Type	Total	Tested	Not Tested	Passed	Failed
● HD	18	18	0	18	0
● SD	97	97	0	97	0

Zone: 1 (EAST)

Zone: 1 (EAST)						
Type	Address	Location	Notes	Last Tested	Test Results	Comments
● SD	32	1FL TOP OF STAIRS		9/4/2025	Pass	
● SD	10	1st FL 101		9/4/2025	Pass	
● SD	12	1st FL 102		9/4/2025	Pass	
● SD	13	1st FL 107		9/4/2025	Pass	
● SD	14	1st FL BY LADYS RM		9/4/2025	Pass	
● SD	25	1st FL BY RM 109		9/4/2025	Pass	



**Davis Ulmer Sprinkler Co**  
55 Riverside Dr  
Corning, NY 14830  
Phone: (607) 936-1500

Zone: 1 (EAST)						
Type	Address	Location	Notes	Last Tested	Test Results	Comments
HD	22	1st FL JANITORS RM		9/4/2025	Pass	
HD	31	1st FL KITCHEN		9/4/2025	Pass	
SD	11	1st FL MAIN ENTRANCE		9/4/2025	Pass	
SD	18	1st FLR 104		9/4/2025	Pass	
SD	27	1st FLR 106 N		9/4/2025	Pass	
SD	23	1ST FLR 105		9/4/2025	Pass	
SD	28	1ST FLR 106 S		9/4/2025	Pass	
SD	19	1ST FLR BY 104		9/4/2025	Pass	
SD	9	1ST FLR BY FACP		9/4/2025	Pass	
SD	17	1st FLR BY KITCHEN		9/4/2025	Pass	
PS	3	1ST FLR BY KITCHEN		9/4/2025	Pass	
PS	02	1ST FLR BY RM 100		9/4/2025	Pass	
PS	1	1ST FLR BY RM 101		9/4/2025	Pass	
PS	6	1ST FLR DRILL HALL N		9/4/2025	Pass	
SD	1	1ST FLR DRILL HALL NW		9/4/2025	Pass	
PS	5	1ST FLR DRILL HALL WEST		9/4/2025	Pass	
PS	14	1ST FLR KITCHEN		9/4/2025	Pass	
WF	11	1ST FLR KITCHEN ANSUL		9/4/2025	Pass	
PS	7	1ST FLR MAIN ENTR		9/4/2025	Pass	
HD	20	1st FLR MENS RM		9/4/2025	Pass	
SD	29	1st FLR OFFICE BY KIT		9/4/2025	Pass	
SD	16	1st FLR RM 103		9/4/2025	Pass	
SD	24	1st FLR RM 108		9/4/2025	Pass	
SD	26	1st FLR RM 109		9/4/2025	Pass	
SD	30	1st FLR SCULLERY		9/4/2025	Pass	
PS	4	1ST FLR SCULLERY		9/4/2025	Pass	
SD	15	1st FLR SUPPLY CLOSET		9/4/2025	Pass	
HD	21	1st FLR WOMANS RM		9/4/2025	Pass	
PS	9	BASEMENT BOILER RM		9/4/2025	Pass	
SD	41	BASEMENT BY ARMS RM		9/4/2025	Pass	
SD	35	BASEMENT BY BATHROOM		9/4/2025	Pass	
PS	8	BASEMENT BY RM 201		9/4/2025	Pass	
PS	10	BASEMENT BY SOUTH EXIT		9/4/2025	Pass	
SD	43	BASEMENT RM 202		9/4/2025	Pass	
SD	34	BASEMENT RM 203		9/4/2025	Pass	
SD	33	BASEMENT RM 203 N		9/4/2025	Pass	



**Davis Ulmer Sprinkler Co**  
55 Riverside Dr  
Corning, NY 14830  
Phone: (607) 936-1500

**Zone: 1 (EAST)**

Type	Address	Location	Notes	Last Tested	Test Results	Comments
● SD	40	BASEMENT RM 206		9/4/2025	Pass	
● SD	42	BASEMENT RM 209		9/4/2025	Pass	
● SD	46	BSMT ARMS RM		9/4/2025	Pass	
● HD	45	BSMT BOILER RM		9/4/2025	Pass	
● HD	38	BSMT ELECTRIC RM		9/4/2025	Pass	
● HD	37	BSMT MENS RM		9/4/2025	Pass	
● SD	44	BSMT RM 203 S		9/4/2025	Pass	
● HD	39	BSMT RM 205		9/4/2025	Pass	
● HD	36	BSMT WOMANS RM		9/4/2025	Pass	
● SD	4	DRILL HALL NE		9/4/2025	Pass	
● SD	2	DRILL HALL NE CENTER		9/4/2025	Pass	
● SD	3	DRILL HALL NE CENTER		9/4/2025	Pass	
● SD	5	DRILL HALL SE		9/4/2025	Pass	
● SD	6	DRILL HALL SE CENTER		9/4/2025	Pass	
● SD	8	DRILL HALL SW		9/4/2025	Pass	
● SD	7	DRILL HALL SW CENTER		9/4/2025	Pass	

**Zone: 2 (West)**

**Zone: 2 (West)**

Type	Address	Location	Notes	Last Tested	Test Results	Comments
■ PS	70	2nd FL STAIR 1		9/4/2025	Pass	
■ PS	82	2nd FL STAIR 2		9/4/2025	Pass	
● SD	3	BASE CORRIDOR WEST		9/4/2025	Pass	
■ PS	6	BSMT CORRIDOR		9/4/2025	Pass	
● SD	4	BSMT CORRIDOR CENTER		9/4/2025	Pass	
● SD	5	BSMT CORRIDOR EAST		9/4/2025	Pass	
● SD	9	BSMT CORRIDOR NORTH		9/4/2025	Pass	
● SD	10	BSMT CORRIDOR NORTH		9/4/2025	Pass	
■ PS	2	BSMT RM 107		9/4/2025	Pass	
■ PS	16	BSMT RM 108		9/4/2025	Pass	
● SD	14	BSMT RM 108 C		9/4/2025	Pass	
● SD	13	BSMT RM 108 EAST		9/4/2025	Pass	
● SD	15	BSMT RM 108 W		9/4/2025	Pass	
● SD	11	BSMT RM 109		9/4/2025	Pass	
● SD	12	BSMT RM 110		9/4/2025	Pass	



**Davis Ulmer Sprinkler Co**  
55 Riverside Dr  
Corning, NY 14830  
Phone: (607) 936-1500

Zone: 2 (West)						
Type	Address	Location	Notes	Last Tested	Test Results	Comments
● SD	7	BSMT STAIR		9/4/2025	Pass	
■ PS	8	BSMT STAIRWELL		9/4/2025	Pass	
● SD	40	CORRIDOR BY 101		9/4/2025	Pass	
● SD	41	CORRIDOR BY 104		9/4/2025	Pass	
● SD	42	CORRIDOR BY 105		9/4/2025	Pass	
● SD	43	CORRIDOR BY 107		9/4/2025	Pass	
● SD	44	CORRIDOR BY 111		9/4/2025	Pass	
● SD	45	CORRIDOR BY 114		9/4/2025	Pass	
■ PS	38	END CORRIDOR		9/4/2025	Pass	
■ PS	46	ENTRY CORRIDOR		9/4/2025	Pass	
● SD	39	Gear RM		9/4/2025	Pass	
■ PS	18	LOBBY		9/4/2025	Pass	
● SD	21	RM 101 A		9/4/2025	Pass	
● SD	22	RM 101 C		9/4/2025	Pass	
● SD	49	RM 101 D		9/4/2025	Pass	
● SD	19	RM 101 E		9/4/2025	Pass	
● SD	20	RM 101 W		9/4/2025	Pass	
● SD	23	RM 102		9/4/2025	Pass	
● SD	24	RM 103		9/4/2025	Pass	
● SD	25	RM 104		9/4/2025	Pass	
● SD	26	RM 104 A		9/4/2025	Pass	
● SD	27	RM 105		9/4/2025	Pass	
● SD	28	RM 106		9/4/2025	Pass	
● SD	29	RM 107		9/4/2025	Pass	
● SD	30	RM 107 B		9/4/2025	Pass	
● SD	31	RM 108		9/4/2025	Pass	
● SD	32	RM 109		9/4/2025	Pass	
● SD	35	RM 111 E		9/4/2025	Pass	
● SD	36	RM 111 W		9/4/2025	Pass	
● SD	50	RM 201		9/4/2025	Pass	
● SD	53	RM 202 A		9/4/2025	Pass	
● SD	54	RM 202 B		9/4/2025	Pass	
● SD	51	RM 202 E		9/4/2025	Pass	
● SD	52	RM 202 W		9/4/2025	Pass	
● SD	55	RM 203		9/4/2025	Pass	
● SD	56	RM 205		9/4/2025	Pass	



**Davis Ulmer Sprinkler Co**  
55 Riverside Dr  
Corning, NY 14830  
Phone: (607) 936-1500

Zone: 2 (West)						
Type	Address	Location	Notes	Last Tested	Test Results	Comments
● SD	57	RM 206		9/4/2025	Pass	
■ PS	47	STAIRWELL 1		9/4/2025	Pass	
■ PS	48	STAIRWELL 2		9/4/2025	Pass	
● SD	72	W 2ND FLR JANITORS CLOSET		9/4/2025	Pass	
● SD	71	W 2ND FLR LANDING		9/4/2025	Pass	
● HD	84	W ATTIC HEATS		9/4/2025	Pass	
● HD	1	W BASEMENT RM 107		9/4/2025	Pass	
● HD	17	W BASEMENT RM 115		9/4/2025	Pass	
● SD	73	W CORR BY 202		9/4/2025	Pass	
● SD	74	W CORR BY 203		9/4/2025	Pass	
● SD	75	W CORR BY 206		9/4/2025	Pass	
● SD	76	W CORR BY 214		9/4/2025	Pass	
● SD	78	W CORR BY 218		9/4/2025	Pass	
● HD	34	W MENS LOCKER RM		9/4/2025	Pass	
● HD	37	W RM 114		9/4/2025	Pass	
● SD	59	W RM 207 E		9/4/2025	Pass	
● SD	58	W RM 207 W		9/4/2025	Pass	
● SD	60	W RM 209		9/4/2025	Pass	
● SD	61	W RM 209 A		9/4/2025	Pass	
● SD	62	W RM 209 B		9/4/2025	Pass	
● SD	63	W RM 213		9/4/2025	Pass	
● SD	64	W RM 214		9/4/2025	Pass	
● SD	65	W RM 216		9/4/2025	Pass	
● SD	66	W RM 218		9/4/2025	Pass	
● DD	67	W RM 220 A		9/4/2025	Pass	
● DD	68	W RM 220 A		9/4/2025	Pass	
● DD	80	W RM 220 B		9/4/2025	Pass	
● DD	81	W RM 220 B		9/4/2025	Pass	
● HD	79	W RM 220 B		9/4/2025	Pass	
● HD	37	W ROOM 114		9/4/2025	Pass	
● HD	69	W ROOM 220 A		9/4/2025	Pass	
● SD	83	W STAIRWELL 2 LANDING		9/4/2025	Pass	
● HD	33	W WOMENS LOCKER RM		9/4/2025	Pass	



**Davis Ulmer Sprinkler Co**  
55 Riverside Dr  
Corning, NY 14830  
Phone: (607) 936-1500

#### Comments

*Any deficiencies or other problems found with the devices must be explained using the comment specific for each device. Additional comments can be added here.*

Please see the summary section at the top of the form for the comments.

#### Inspector's Information

Inspected By

Justin Button

Inspector License:

N/A

I state that the information on this form is correct at the time and place of my inspection, and that all equipment tested at this time was left in operating condition upon completion of this inspection except as noted in the *Comments*.

Signature of Inspector

A handwritten signature in black ink that appears to read "J. Button".

Date

9/4/2025

#### **SECTION IV - OTHER TERMS AND LIMITATIONS**

1. This Agreement is for inspection services only. If Customer wants Company to make any repairs, alterations or replacements as a result of the inspection services performed pursuant to this Agreement, such work and the additional compensation to Company must be specified in a separate written agreement between Company and Customer.
2. Any additional system equipment added to the Property after the date of this Agreement or not otherwise specified in Section II of this Agreement is not included in the inspection services to be provided pursuant to this Agreement. Inclusion of any such other equipment will require execution of an amendment to this agreement and adjustment of the inspection fee.
3. The inspection services provided by Company pursuant to this Agreement are limited to an evaluation of the functionality of the equipment identified in Section II above. Company will not evaluate or express any opinion as to whether the design and/or installation of the system are suitable for the Property or the operations at the Property.
4. Company's inspection is limited to a visual inspection of external readily accessible parts of the system and will not include every component including but not limited to sprinkler heads, pipe, fittings, hangers, pull stations, smoke detectors, conduit wire or other parts of the system being inspected. Company will only inspect a representative number or sample of the sprinkler heads, pipes, hangers, valves or other devices and equipment in their current position. THEREFORE, BY CONDUCTING ITS INSPECTION UNDER THIS AGREEMENT, COMPANY DOES NOT GUARANTEE OR WARRANT THE CONDITION OR OPERATION OF EVERY PIPE, SPRINKLER HEAD OR OTHER PART OF THE FIRE PROTECTION AND/OR FIRE ALARM/SECURITY SYSTEM ON THE PROPERTY.
5. AS A MATERIAL INDUCEMENT FOR COMPANY TO PROVIDE THE SERVICES SPECIFIED IN THIS AGREEMENT AT THE INSPECTION FEE QUOTED IN THIS AGREEMENT, CUSTOMER AGREES THAT COMPANY'S LIABILITY TO CUSTOMER AND ALL THIRD PARTIES WITH RESPECT TO ANY CLAIM UNDER THIS AGREEMENT, OR ARISING FROM THE SERVICES FURNISHED BY COMPANY, SHALL BE LIMITED TO THE LESSER OF \$1,000.00 OR THE TOTAL CONSIDERATION ACTUALLY RECEIVED BY COMPANY UNDER THIS AGREEMENT. THE FOREGOING LIMITATION SHALL APPLY TO ALL CLAIMS REGARDLESS OF THE NATURE THEREOF, INCLUDING CLAIMS ASSERTED AS A BREACH OF CONTRACT, A BREACH OF WARRANTY, NEGLIGENCE, STRICT LIABILITY OR OTHERWISE. IN NO EVENT SHALL COMPANY BE LIABLE FOR INCIDENTAL, CONSEQUENTIAL, SPECIAL, AND INDIRECT OR PUNITIVE DAMAGES, OR DAMAGES FOR LOST PROFITS. If Customer desires Company to accept an increased limit of liability for the services provided under this Agreement, Company will provide an alternate inspection fee quote reflecting such increased limit, provided, however, that the increased limit shall be effective only upon Company's and Customer's execution of a replacement agreement confirming the same and Customer's payment of the alternate fee.
6. Company, following each inspection, will provide to Customer a written "Report of Inspection" ("Report"). If required and/or with prior written authorization, Company will provide copies of the Report to the local or state authority having jurisdiction on behalf of Customer. If requested by Customer, a copy of the Report will also be forwarded to Customer's insurance company. The Report and recommendations, if any, by Company are only advisory in nature and are intended to assist Customer in reducing the possibility of loss to the Property by indicating obvious defects or impairments to the system(s) which were discovered by Company's inspection and which should receive prompt attention.

7. Customer agrees to obtain and shall be solely responsible to maintain property and casualty insurance for the Property, all contents therein, and operations performed within or around the Property. No insurance company, insurer or bonding company or their successors or assigns shall have any right of subrogation or otherwise against Company arising out of this Agreement or the services provided by Company pursuant to this Agreement.
8. Customer agrees to indemnify, defend and hold harmless Company, its agents, and employees from and against any and all claims, demands, suits, liabilities, damages, judgments, losses and expenses (including, without limitation, attorneys' fees) which may be asserted against or incurred by Company by any third party arising out of or related to this Agreement or the services provided by Company pursuant to this Agreement.
9. Company will make every reasonable effort to prevent the discharge of water into or onto areas of landscaping, decorative pavement, etc., at the Property, however it is Customer's responsibility to provide sufficient and readily accessible means to accept the full flow of water that may be required by tests as determined by the type of inspection and to take measures to eliminate the formation of ice in any area where a slip and fall hazard could occur.
10. This Agreement may not be assigned by Customer without the written consent of Company.
11. This Agreement may be signed in counterparts; a signed facsimile, photocopy, and/or electronic mail of this Agreement shall be as binding on both parties just as though this Agreement were executed in its original, pre-printed form.
12. This Agreement constitutes the entire Agreement between Company and Customer regarding the subject matter hereof and supersedes all prior agreements and understandings relating thereto. Although Customer for its convenience or in furtherance of its internal procedures may issue to Company a purchase order, order acknowledgement or similar form in connection with the services provided by Company pursuant to this Agreement, no term or condition in any such form that is different from or in addition to the terms set forth in this Agreement shall be applicable, and all such different or additional terms shall be ineffective and void. This Agreement cannot be amended or modified except by a writing signed by Customer and Company.
13. Customer acknowledges Company is relying upon the accuracy of the information regarding Customer and the Property set forth in Sections I of this Agreement. Customer represents that all such information is complete and accurate as of the date on which this Agreement is signed by Customer. Customer will promptly advise Company in writing of any change to such information.
14. Other inclusions, exclusions, or attachments (if any) we exclude fire alarm.