

Fire Extinguisher Inspection List



Location Code: GQVGTRJ

Contact: CINDY CROYLE

Contact Address: 410 MILLER AVE
NEW CASTLE, PA 16101-1451

Phone: 412-477-7816

Email: cynthia.a.croyle.ctr@army.mil,
reginald.cook@cmimgmt.com

Property Evaluated: USAR PA063 NEW CASTLE (Business)
410 MILLER AVE
NEW CASTLE, PA 16101-1451

Description: Fire Extinguishers (USAR PA063 NEW CASTLE A 4-25
EXT)

Work Order: SV2503190286L

Company: GRUNAU FIRE PROTECTION

Address: 590 E WESTERN RESERVE RD, BLDG 5
BOARDMAN, OH 44514

Company Phone: 330-758-3500

Inspector: KEVIN JUILLERAT
OH FIRE - 54.50.1882

Date of Work: 4/24/2025

Frequency: Annual

Deficiency Summary

Status: Open

Fire extinguisher deficiency for Tag # 2, Serial Number: 39869EF, Model: Ansul CD-10, Size: 15#, Type: Co2.

DUE FOR HYDROSTATIC TEST

Status: Open

Fire extinguisher deficiency for Tag # 5, Serial Number: BE-735892, Model: Amerex B456, Size: 10#, Type: ABC.

Due for hydrostatic test

Status: Open

Fire extinguisher deficiency for Tag # 18, Serial Number: AD-784984, Model: Buckeye 20S HI SA, Size: 20#, Type: ABC.

Due for 6 yr maintenance

Service Summary

Total Extinguishers: 19, Tested: 19, Not Tested: 0, Passed: 16, Failed: 3

Overdue: 1 is due for 6 yr service.
1 is due for Hydro service.

In 2027: 2 are due for 6 yr service.
6 are due for Hydro service.

In 2025: 1 is due for Hydro service.

In 2028: 2 are due for 6 yr service.

In 2026: 2 are due for 6 yr service.
1 is due for Hydro service.

In 2030: 3 are due for 6 yr service.

General Comments

These items are outside the regular scope of the required inspection and are not the result of an engineering review. This information is not intended to be all-inclusive but rather a list of items discovered as a by-product of the required inspection.

There are no general comments for this submission

Fire Extinguisher Inspection List

Account Information		
Facility Name: USAR PA063 NEW CASTLE	Property Type: Business	Location Code: GQVGTRJ
Service Address: 410 MILLER AVE, NEW CASTLE, PA, 16101-1451		
Owner: CINDY CROYLE	Owner's Phone: 412-477-7816	
Owner's Address: 410 MILLER AVE, NEW CASTLE, PA, 16101-1451		

Zone: N1

Zone: N1										
Tag	Serial Number	Model	Size	Type	Location	Last Service	Next Service	Frequency	Inspection	Comments
4	H07793918	Buckeye (2022) 10 HI SA80	10#	ABC	122 GYM	New 2022	6 yr 2028	Annual	Pass	
6	I-14558795	Amerex (2007) C260	6L	K	MAIN BUILDING KITCHEN	New 2024	6 yr 2030	Annual	Pass	
7	LV046309	Amerex (1993) A479	5#	PURPLE K	MAIN BUILDING KITCHEN	Hydro 2021	6 yr 2027	Annual	Pass	
8	LV-046113	Amerex (1993) A479	5#	PURPLE K	MAIN BUILDING ASSEMBLY	Hydro 2021	6 yr 2027	Annual	Pass	
9	CG-623427	Amerex (2014) B456	10#	ABC	MAIN BUILDING ASSEMBLY	6 yr 2021	Hydro 2027	Annual	Pass	
10	CG-611429	Amerex (2014) B456	10#	ABC	MAIN BUILDING ASSEMBLY	6 yr 2021	Hydro 2027	Annual	Pass	
11	CG-611408	Amerex (2014) B456	10#	ABC	MAIN BUILDING MECHANICAL ROOM	6 yr 2021	Hydro 2027	Annual	Pass	
12	A-23953990	Amerex (2014) B456	10#	ABC	MAIN BUILDING ASSEMBLY	6 yr 2021	Hydro 2027	Annual	Pass	
13	A-23950549	Amerex (2014) B456	10#	ABC	MAIN BUILDING ASSEMBLY	6 yr 2021	Hydro 2027	Annual	Pass	
14	F91393283	Badger (2020) ADV-10	10#	ABC	MAIN BUILDING CORRIDOR NEAR FACP	New 2020	6 yr 2026	Annual	Pass	
15	A-23950548	Amerex (2014) B456	10#	ABC	MAIN BUILDING CORRIDOR	6 yr 2021	Hydro 2027	Annual	Pass	
16	I19011236	Buckeye (2024) 10 HI SA80	10#	ABC	CLASSROOM 104	New 2024	6 yr 2030	Annual	Pass	

Zone: N3

Zone: N3											
Tag	Serial Number	Model	Size	Type	Location	Last Service	Next Service	Frequency	Inspection	Comments	
1	S-174365	Ansul (1972) CD-10	15#	Co2	OMS BUILDING	Hydro 2021	Hydro 2026	Annual	Pass		
2	39869EF	Ansul (1976) CD-10	15#	Co2	OMS BUILDING	Hydro 2018	Hydro 2023	Annual	Fail	DUE FOR HYDROSTATIC TEST	
3	F92889611	Buckeye (2020) 10 HI SA80	10#	ABC	OMS BUILDING	New 2020	6 yr 2026	Annual	Pass		
5	BE-735892	Amerex (2012) B456	10#	ABC	OMS BUILDING	6 yr 2019	Hydro 2025	Annual	Fail	Due for hydrostatic test	
17	JL-484937	Amerex (190) 456	10#	ABC	OMS BUILDING UTILITIES ROOM	Hydro 2021	6 yr 2028	Annual	Pass		
18	AD-784984	Buckeye (2010) 20S HI SA	20#	ABC	OMS BUILDING	New 2010	6 yr 2016	Annual	Fail	Due for 6 yr maintenance	
19	I-30403638	Amerex (2024) 423	20#	ABC	OMS BUILDING	New 2024	6 yr 2030	Annual	Pass		

Comments

Any deficiencies or other problems found with the extinguishers must be explained using the comment specific for each extinguisher. Additional comments can be added here.

Please see the summary section at the top of the form for the comments.

Inspector's Information

Inspected By

KEVIN JUILLERAT

Inspector License:

OH FIRE - 54.50.1882

I state that the information on this form is correct at the time and place of my inspection, and that all equipment tested at this time was left in operating condition upon completion of this inspection except as noted in the *Comments*.

Signature of Inspector



4/24/2025

Date

Owner or Owner's Representative

Owner or Owner's Representative Name

No Signature Available

Owner or Owner's Representative Signature

Date

4/24/2025