

Date:

Region:

CSS No.:

FAC ID:

Maximo WO No.:

Asset #:

Priority:



Original Work Request:

Repair by replacing the aluminum framed window in the ARA office. Window is broken/cracked. Recommended Contractor: Window contractor Kevin (304) 276-9679

Description of Repairs Needed:

Investigation to assess replacing cracked aluminum framed window.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1) labor and travel to investigate	1	\$ 500.00	\$ 500.00
			\$ -

Material List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$500.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$500.00	\$60.00	\$30.00	\$590.00