

Date: 4-23-25

Region: 4C

FEMS/CSS No.: 94841

FAC ID: VA001

Maximo WO No.: 18796

Asset #:

Priority: 2



Original Work Request:

Repair by replacing the aluminum framed window in the aRA office. Window is broken/cracked. Recommended contractor: Kevin (304) 276-9679

Description of Repairs Needed:

Proposal is to remove and dispose of one existing window and frame and furnish and install new window and frame. All glass will be tempered safety glass. Will seal both exterior and interior of the new windows as needed. Lead time is 12-14 weeks from date of order.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	6	\$ 250.00	\$ 1,500.00
Travel/Hotel/Per Diem	1	\$ 490.00	\$ 490.00
			\$ -

Material List:

	Quantity	Cost	Total
Kawneer black aluminum double hung window with clear glass and half screen	1	\$ 3,813.00	\$ 3,813.00
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,990.00	\$3,813.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$5,803.00	\$696.36	\$348.18	\$6,847.54