

Date:

Region:
FAC ID:

CSS No.:
Maximo WO No.:

Asset #:

Priority:



Original Work Request:

Both toilets in the female latrine and 2 toilets in the men's latrine need seated and sealed along with cleaning the flush valves

Description of Repairs Needed:

Replace sloan valve in Women's latrine (1st stall)

Labor:

	Labor Hrs	Labor Rate	Total
1 Tech	1.5	\$ 100.00	\$ 150.00
			\$ -

Material List:

	Quantity	Cost	Total
Sloan Regal Flush Valve 1.6 gpf, 11-1/2	1	\$ 193.45	\$ 193.45
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$150.00	\$193.45	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$343.45	\$41.21	\$20.61	\$405.27