

## OVER AND ABOVE FUNDING

**Region:** 5

**Location:** VA002

**CSS #:**29411

**Maximo Work Order No.:** 13872

**Asset #:** NA

**Date Issued:** 03/10/2021

**Original Description:** Carbon Monoxide sensors will need to be installed in each boiler room for the boilers to Pass annual certification in October

**Repairs Needed:**

S&S proposes to install carbon monoxide sensors with alarms in the boiler mechanical room

**RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):**

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	Parts (See detail in attached quote)	--	--	\$2,635.57	--	\$2,635.57
--	NA	SS Labor	56	\$100.00	--	--	\$5,600.00

**Estimate Summary:**

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
56	\$5,600.00	\$2,635.57	NA	\$8,235.57	106%	<b>\$8,729.70</b>