

Additional Funding Request

Submitted: 11/03/2021

VA002- Boiler #3 safety valve	CSS #33282 WO#15402											
Description of Repairs	S&S proposes to remove and replace the safety valve on boiler #3. S&S will then complete a system check to ensure it is running properly.											
Original SC Investigative Diagnosis	NA											
Diagnosis: Initial Work Order	Replace the safety valve on boiler #3											
Explanation of Additional Costs for Repairs	N/A											
Additional Material Cost to Perform Repairs	Materials: \$ 201.51 <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">Water Pressure Relief Valve/Shipping</td> <td style="text-align: left; padding: 2px;">1</td> <td style="text-align: left; padding: 2px;">\$201.51</td> <td style="text-align: left; padding: 2px;">\$201.51</td> </tr> </tbody> </table>				ITEM	QUANTITY	UNIT PRICE	TOTAL	Water Pressure Relief Valve/Shipping	1	\$201.51	\$201.51
ITEM	QUANTITY	UNIT PRICE	TOTAL									
Water Pressure Relief Valve/Shipping	1	\$201.51	\$201.51									
Additional Labor Cost to Perform Repairs	Labor: \$600.00 6 hours each/HVAC Rate \$100.00 per hour = \$600.00											
Total Cost of Repair	\$801.51											