

**Region: 5**

**Location: VA002**

**CSS # 35208**

**Maximo Work Order No.:16911**

**Asset #: 2226HWTP#01**

**Date Issued: 03/29/2022**

**Original Description:Hot water booster pump Turning on and off about every 3 minutes, very hot, and rattling noise**

**Repairs Needed:**

Troubleshoot B&G hot water booster pump. Tried greasing, cleaning and repositioning internal parts with no success. The pump appears to be stalling out immediately after activation. S&S will remove and replace the booster pump and then complete a system check to ensure everything is working properly.

\*Pump is in stock

**RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):**

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	Part LF1/12HP 100BNFI CIRC PUMP 115V	--	--	\$1,200.86	--	\$1,200.86
--	NA	Shipping	--	--	\$100.00	--	\$100.00
--	NA	Diagnostic	1	\$450.00			\$450.00
--	NA	Labor	16	\$100.00	--	--	\$1,600.00

**Estimate Summary:**

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
17	\$2,050.00	\$1,300.86	NA	\$3,350.86	100%	<b>\$3,350.86</b>