

Over and Above Estimate

Region: 5

Location: VA002

CSS #: 25257

Asset #:

Maximo Work Order No.: 12326

Date Issued: 6/3/20

Original Description: CHILLER - Found circuit 2 compressor 1 contactor in need of replacement or rebuild kit.

Repair Needed: While onsite performing PMs, S&S diagnosed Circuit 2 Compressor 1 had faulty contactors.

S&S proposes to remove and replace the faulty contactors, S&S will then perform a system check to ensure everything is working properly.

Non Pre-Priced Estimate:

Quantity	Line Item Number	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1	N/A	HVAC Labor Rate / 9 hours @ \$100 hr	9		\$100.00			\$900.00
2	N/A	Contactor 600VAC 80 AMP		\$351.98		\$703.96		\$703.96
2	NA	Contactor 115A 600V		\$464.46		\$928.92		\$928.92
1	NA	Tax		\$81.64		\$81.64		\$81.64
1	NA	Shipping		\$100.00		\$100.00		\$100.00

Note: RS Means (Pre-Priced) not used in compiling this estimate.

Note: Subcontractor quote attached.

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	-PM COST	Total Cost	CE Factor	Total Estimate
9	\$900.00	\$1,814.52	(\$250)	\$2464.52	100%	\$2,464.52

Note: