

Additional Funding Request

Site: VA009	WO#6472 CSS # 16511 Asset# 2259
Description of Repairs	Replace Safety Relief Valve
Diagnosis: Initial Work Order CSS# 16511	Replace Safety Relief Valve to allow for boiler certification
Explanation of Additional Costs for Repairs	Labor and Material to replace pressure relief valve
Additional Labor Cost to Perform Repairs	6x\$120.00- \$720.00
Additional Material Cost to Perform Repairs	\$129.49
Total Cost of Repair	\$849.49-250.00(CM)= \$599.49



P.O. Box 119 • Altavista, VA 24517 • 24 Hour Service: 800.789.7199 • Fax: 888.722.2712 • MooresElectric.com

Proposal

October 30, 2018

Quotes are valid for 30 days.

ISG USARC VA009	Contact Name	George Grant
3502 Bennett Creek Park Rd.,	Telephone	
Suffolk, VA 23345	Cell Phone	304.663.8670
Email ggrant@internationalsupportgroup.com	Fax Number	

DESCRIPTION OF EQUIPMENT:

Make: Munchkin
Model: 199M R2
Serial: F01Q24274

DESCRIPTION OF PROBLEM:

Checked in and waited for inspector, inspector came and checked out operation. Noted temperature and pressure relief is leaking and will need to be replaced to finalize inspection. Will submit quote to replace.

DESCRIPTION OF REPAIRS:

Technician will return to site to replace the temperature and pressure relief valve, flush out air in lines and verify operations.

Note: Parts have a 3 to 5 day leadtime.

MATERIAL, EQUIP OR PARTS

	Quantity	Sell price
Relief Valve	1.00	\$ 29.97
Misc. Materials	1.00	\$ 25.44
Shipping	1.00	\$ 19.08
Truck Fee	1.00	\$ 55.00
Material Total		\$ 129.49

LABOR ITEMIZED

			Labor
Labor - One Man	6	\$ 120.00	\$ 720.00
Labor - Second Man	0	\$ 120.00	\$ -
		Labor Total	\$ 720.00

Thank you for your business. If you have any questions or concerns, please feel free to contact us via telephone or quotes@mooreselectric.com

Materials	\$ 129.49
Labor	\$ 720.00
TOTAL	\$ 849.49

*This does not include
original call cost.*

Robert Lowery, Changeout Estimator 434-309-2591
Amy Hockaday, Estimator 434-309-2569
James Davis, Estimator 434-309-2568
Adam Barker, Estimator 434-369-3514
Jared Underwood, Estimator 434-306-2446

Approved by: _____

Standard Terms and Conditions

Payments past 30 days are subject to 1.5% monthly service charge on unpaid balance. Additional charges for payments made through credit cards may apply. Late payments sent to collections or legal process the purchaser agrees to pay all costs, expenses, and reasonable attorney fees.

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VA009 Date of Visit: 10/29/18
Contractor Personnel on Site:

1. Jacob Long 2. Bryan Mayo

Work Performed: Met with Boiler inspector to tear down and allow for inspection

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO# 5909/5910

Service Calls - Service Call Number and Description


1. CSS# 5909
2. CSS# 5910
3. CSS#

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Jacob Long

Date: 10/29/18


Signed: 

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: St. Myer, Glenn SFC

Date: 10/29/18

Signed: 

E-Mail: glenn.p.stmyer.mil@ngil.mil

IMPORTANT

SER.
NO.

MODEL M1

WATTS

N. Andover, MA 01845

NO. M335

SIZE 3/4 IN.

SET 30 PSIG

B.T.U. PER HR. RATING



ASME

510,000

CANADIAN REGISTRATION NO.

OG7543.5C

----- Original message -----

From: Marvin Slaughter <mslaughter@mooreselectric.com>

Date: 10/30/18 9:45 AM (GMT-05:00)

To: George Grant <ggrant@internationalsupportgroup.com>

Subject: FW: International Support Group - VA009 | Unit #2 | Proposal

George –

Please see the attached valve photo.

Item	Description	Quantity	Net Price	UM	Total
WM335M2030F	*NP 3/4 BRZ MXF BLR PR. VLV 30 PSI	2	23.562	EA	47.

Thanks,

Marvin Slaughter

Service Estimator

101 Edgewood Ave. | Altavista, VA 24517

O. 434.369.3514 | mooreselectric.com

