

## Additional Funding Request

| Site: VA009                                    | WO#6472      CSS # 16511      Asset# 2259                     |
|------------------------------------------------|---------------------------------------------------------------|
| Description of Repairs                         | Replace Safety Relief Valve                                   |
| Diagnosis: Initial Work Order<br>CSS# 16511    | Replace Safety Relief Valve to allow for boiler certification |
| Explanation of Additional Costs<br>for Repairs | Labor and Material to replace pressure relief valve           |
| Additional Labor Cost to<br>Perform Repairs    | 3x\$120.00- \$360.00                                          |
| Additional Material Cost to<br>Perform Repairs | \$129.49                                                      |
| Total Cost of Repair                           | \$489.49-250.00(CM)= \$239.49                                 |
|                                                |                                                               |
|                                                |                                                               |



P.O. Box 119 • Altavista, VA 24517 • 24 Hour Service: 800.789.7199 • Fax: 888.722.2712 • MooresElectric.com

## Proposal

October 30, 2018

Quotes are valid for 30 days.

|                                                                                                      |              |              |
|------------------------------------------------------------------------------------------------------|--------------|--------------|
| ISG USARC VA009                                                                                      | Contact Name | George Grant |
| 3502 Bennett Creek Park Rd.,                                                                         | Telephone    |              |
| Suffolk, VA 23345                                                                                    | Cell Phone   | 304.663.8670 |
| Email <a href="mailto:ggrant@internationalsupportgroup.com">ggrant@internationalsupportgroup.com</a> | Fax Number   |              |

### DESCRIPTION OF EQUIPMENT:

Make: Munchkin  
Model: 199M R2  
Serial: F01Q24274

### DESCRIPTION OF PROBLEM:

Checked in and waited for inspector, inspector came and checked out operation. Noted temperature and pressure relief is leaking and will need to be replaced to finalize inspection. Will submit quote to replace.

### DESCRIPTION OF REPAIRS:

Technician will return to site to replace the temperature and pressure relief valve, flush out air in lines and verify operations.

Note: Parts have a 3 to 5 day leadtime.

### MATERIAL, EQUIP OR PARTS

|                       | Quantity | Sell price       |
|-----------------------|----------|------------------|
| Relief Valve          | 1.00     | \$ 29.97         |
| Misc. Materials       | 1.00     | \$ 25.44         |
| Shipping              | 1.00     | \$ 19.08         |
| Truck Fee             | 1.00     | \$ 55.00         |
| <b>Material Total</b> |          | <b>\$ 129.49</b> |

### LABOR ITEMIZED

|                    |   | Labor               |
|--------------------|---|---------------------|
| Labor - One Man    | 3 | \$ 120.00 \$ 360.00 |
| Labor - Second Man | 0 | \$ 120.00 \$ -      |
| <b>Labor Total</b> |   | <b>\$ 360.00</b>    |

Thank you for your business. If you have any questions or concerns, please feel free to contact us via telephone or [quotes@mooreselectric.com](mailto:quotes@mooreselectric.com)

|                  |                  |
|------------------|------------------|
| <b>Materials</b> | <b>\$ 129.49</b> |
| <b>Labor</b>     | <b>\$ 360.00</b> |
| <b>TOTAL</b>     | <b>\$ 489.49</b> |

*This does not include  
original call cost.*

Robert Lowery, Changeout Estimator 434-309-2591  
Amy Hockaday, Estimator 434-309-2569  
James Davis, Estimator 434-309-2568  
Adam Barker, Estimator 434-369-3514  
Jared Underwood, Estimator 434-306-2446

Approved by: \_\_\_\_\_

#### Standard Terms and Conditions

Payments past 30 days are subject to 1.5% monthly service charge on unpaid balance. Additional charges for payments made through credit cards may apply. Late payments sent to collections or legal process the purchaser agrees to pay all costs, expenses, and reasonable attorney fees.

### CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VA009 Date of Visit: 10/29/18  
Contractor Personnel on Site:

1. Jacob Long 2. Bryan Mayo

**Work Performed: Met with Boiler inspector to tear down and allow for inspection**

**Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)**

1. WO# 5909/5910

**Service Calls - Service Call Number and Description**


1. CSS# 5909  
2. CSS# 5910  
3. CSS# \_\_\_\_\_

### CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Jacob Long

Date: 10/29/18


Signed: 

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: St. Myer, Glenn SFC

Date: 10/29/18

Signed: 

E-Mail: glenn.p.stmyer.mil@ngil.mil

IMPORTANT

SER. NO.    
MODEL M1

**WATTS**

N. Andover, MA 01845

NO. M335  
SIZE 3/4 IN.  
SET 30 PSIG  
B.T.U. PER HR. RATING  
  **ASME**  
510,000  
CANADIAN REGISTRATION NO.  
OG7543.5C

----- Original message -----

From: Marvin Slaughter <[mslaughter@mooreselectric.com](mailto:mslaughter@mooreselectric.com)>

Date: 10/30/18 9:45 AM (GMT-05:00)

To: George Grant <[ggrant@internationalsupportgroup.com](mailto:ggrant@internationalsupportgroup.com)>

Subject: FW: International Support Group - VA009 | Unit #2 | Proposal

George –

Please see the attached valve photo.

| Item        | Description                        | Quantity | Net Price | UM | Total |
|-------------|------------------------------------|----------|-----------|----|-------|
| WM335M2030F | *NP 3/4 BRZ MXF BLR PR. VLV 30 PSI | 2        | 23.562    | EA | 47.   |

Thanks,

**Marvin Slaughter**

Service Estimator

101 Edgewood Ave. | Altavista, VA 24517

O. 434.369.3514 | [mooreselectric.com](http://mooreselectric.com)

