

Date: 4-10-24

Region: 4C

CSS No.: 97460

FAC ID: VA012

Maximo WO No.: 15437

Asset #: [ ]

Priority: 2



**Original Work Request:**

CMI has requested a CSS ticket for the Fire Inspection Deficiencies noted by the contractor.

**Description of Repairs Needed:**

Perform 5 year internal inspection on all systems. Perform 5 year FDC hydro, install FDC sign, install lock and chain to control valves. All performance objectives are conducted in accordance with the applicable edition of NFPA #25 standard for the inspection, testing and maintenance of water based systems in compliance with the International Fire Code. Inspection and testing conducted in accordance with this contract shall not be considered an engineering review of the fire protection system.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (3) - see attached quote for labor scope	24	\$ 158.69	\$ 3,808.56
			\$ -

**Material List:**

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

**Equipment List:**

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

**PM WO History:**



**Estimate Summary:**

Labor	Material	Equipment
\$3,808.56	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$3,808.56	\$457.03	\$228.51	\$4,494.10